

$$\sqrt{R_{Z40}} \text{ (V)}$$

Спраб. №

Technical drawing of a mechanical part, showing a cross-section and a side view.

Dimensions and Features:

- Outer diameter: $\varnothing 28_{-0.4}^{+0.4}$
- Inner diameter (hole): $\varnothing 18_{-0.4}^{+0.4}$
- Flange thickness: 3.5 ± 0.2
- Flange width: 15
- Flange fillet radius: $R1.6^{**}$
- Chamfer: $2 \times 45^\circ$
- Surface finish: $G 3/4-B \sqrt{R\phi 6.3}$
- Section line: A

Technical drawing of a hexagonal nut. The drawing shows a hexagonal base with concentric circles representing the threads. Key dimensions and features include:

- Overall width across flats: 47.3^*
- Overall height: 49^*
- Threaded section height: 23
- Threaded section outer diameter: $\phi 2.02$
- Threaded section inner diameter: 2 омб.
- Threaded section width: 2.5
- Threaded section inner diameter: $\phi 3^{**}$
- Surface finish symbol: $\sqrt{Ra 12.5}$
- Surface finish symbol: ϕ

1* Размеры для справок.
2** Размеры обеспечить инструментом.
3 Общие допуски по ГОСТ 30893.1 - с.
4 Остальные технические требования по ГОСТ 16078-70.

Распечатано с ДЗ ДОС_ID: -9829296 Версия: 0

4497.90.36.024

Шмугаер

01	0.19	2:1
----	------	-----

0.19	2:1
------	-----

2:1

Инв. № подл.	Подп. и дата	Взам. инв. №	Инв. № дубл.	Подп. и дата
616547				

[illegible]

4497.90.36.024.dwg

Конуробадн

Формат А3