



6,33_{-0,01}

2,36^{+0,01}

0,5

0,5

2

0,5

R1,5

R1

0,5

18,5_{-0,02}

19

26

0,5×45°

M3-6g

R2

1,25√